

# Metadata

|                                     |  |
|-------------------------------------|--|
| <b>Standardized Instrument Name</b> |  |
| <b>Scheme URI</b>                   |  |
| <b>Term URI</b>                     |  |
| <b>Instrument DOI</b>               |  |
| <b>Instrument Unique ID</b>         | 20775991   |
| <b>ID Type</b>                      | Serial No.   |
| <b>Model No.</b>                    | U26-001  |
| <b>Instrument Type</b>              | Baseline   |
| <b>Description</b>                  | Onset HOBO oxygen logger measures oxygen and temperature values. |
| <b>Manufacturer</b>                 | Onset  |
| <b>Manufacturer type</b>            | Organizational   |
| <b>Notes</b>                        |  |
| <b>Sensor Details</b>               |  |
| <b>Sensor Details 1</b>             |  |
| <b>Instrument Sensor Name</b>       | HOBO Dissolved Optical Oxygen Sensor                             |
| <b>Instrument Sensor Serial No.</b> | 20775991   |
| <b>Sensor Range</b>                 | 0 - 20 mg/L; 320 to 95°F (0 to 35°C)                             |
| <b>Sensor Sensitivity</b>           |  |
| <b>Sensor Units</b>                 | mg/L   |
| <b>Last Calibration Date</b>        |  |
| <b>Sensor Details 2</b>             |  |
| <b>Instrument Sensor Name</b>       | HOBO Temperature Sensor  |
| <b>Instrument Sensor Serial No.</b> | 207759901  |
| <b>Sensor Range</b>                 | 23 to 104°F (-5 to 40°C); non-Freezing                           |
| <b>Sensor Sensitivity</b>           | 0.2  |
| <b>Sensor Units</b>                 | Degrees Celsius  |
| <b>Last Calibration Date</b>        |  |